



VOLVO V60: 1FFS805

Vinnumber:	YV1FW84A1D1134503	Versionname:	V60 D2 Kinetic St/St 115PK
First Registrationdate:	17/06/2013	Fiscalpower:	
Expertise Mileage:	140966	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4707
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/45/17/97 W LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1081,96
Door frame R L, Scratch(es), Acceptable	0,00



Wing R R, Dent(s), Acceptable

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00



Bumper corner R L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), It - Spot repair

115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Windscreen, Broken, E - Replace

487,20

