



BMW 3 TOURING: 1KSJ253

Vinnumber:	WBA3L11010K177828	Versionname:	2.0 320D EFFICIENTDYN. (120KW) TOURING
First Registrationdate:	23/06/2015	Fiscalpower:	
Expertise Mileage:	63910	Power Kw:	120
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3229,17
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Deformed / Strained, Le - Replace and paint	651,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08





Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Rearview mirror basis R, Scratch(es), Smart repair

110,64



Roof, Chemical polution, LI - Repair and paint (complete)

481,50

