



**LU AUDI a3 Sportback: YL4549**

Vinnumber:	<b>WAUZZZ8V4HA094503</b>	Versionname:	<b>1.6 TDI 81kW Sport S tronic</b>
First Registrationdate:	<b>25/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>68769</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1404</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

<b>Total cost ex VAT</b>	<b>1201,78</b>
--------------------------	----------------

<b>Bumper F, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 174,00



Wing F R, Dent(s), LI - Repair and paint (complete) 244,18



Rearview mirror housing L, Scratch(es), Paint 75,00



Tyre repair kit, Missing, E - Replace 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tires, Flat, Repair/replace (lump sum) 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

