



AUDI A3: 1FIH739

| | | | |
|-------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WAUZZZ8V6EA017420 | Versionname: | A3 SB Attraction 105PK |
| First Registrationdate: | 5/07/2013 | Fiscalpower: | |
| Expertise Mileage: | 90602 | Power Kw: | 77 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OVER 27400 KM | Parking lot: | 1704 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--------------------------|
| GPS storage | | Central consol F | |
| GPS storage | SD | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | Tow bar removable |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 393,56 |
|-------------------|---------------|

| | |
|---------------------------------|--------------|
| Seat cover F R, Stain, Cleaning | 25,00 |
|---------------------------------|--------------|



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), It - Spot repair 115,56



Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Bumper R, Scratch(es), Acceptable 0,00

