



AUDI A3: 1GIC216

| | | | |
|------------------------------------|-------------------------|--------------|-----------------------------|
| Vinnumber: | WAUZZZ8VXE133980 | Versionname: | A3 SB Ambiente 136PK |
| First Registrationdate: | 13/02/2014 | Fiscalpower: | |
| Expertise Mileage: | 78213 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2528 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Sun Roof electric |
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Seats F heated | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

Assistance equipment

| | | | |
|--|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 930,15 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



Door F R, Chemical polution, LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Luggage space cover, Incomplete, Repair/replace (lump sum) 20,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

