



**AUDI A4 AVANT: 1NUJ193**

|                                    |                         |              |                      |
|------------------------------------|-------------------------|--------------|----------------------|
| Vinnumber:                         | <b>WAUZZF43GA088622</b> | Versionname: | <b>2.0 TDI 100KW</b> |
| First Registrationdate:            | <b>28/04/2016</b>       | Fiscalpower: |                      |
| Expertise Mileage:                 | <b>69788</b>            | Power Kw:    | <b>100</b>           |
| Bodytype:                          |                         | Body color:  | <b>Black</b>         |
| Gearbox:                           | <b>MAN 6 VIT</b>        | Paint type:  | <b>Metalic</b>       |
| Transmission:                      | <b>Front</b>            | Rims summer: | <b>Aluminium</b>     |
| Fueltype:                          | <b>Diesel</b>           | Oil level:   | <b>OK</b>            |
| Battery functioning:               | <b>Yes</b>              | Parking lot: | <b>3531</b>          |
| Number of doors:                   | <b>5</b>                |              |                      |
| Number of seats:                   | <b>5</b>                |              |                      |
| Number head rests:                 | <b>5</b>                |              |                      |
| Rims summer:                       | <b>Aluminium</b>        |              |                      |
| Category:                          | <b>Passenger Car</b>    |              |                      |
| Oil level:                         | <b>OK</b>               |              |                      |
| Registration Certificate Car (BE): | <b>Yes</b>              |              |                      |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Seats F heated                 | <b>No Tow bar</b>            |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/60/16/92 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                   |       |
|-------------------|-------|
| Total cost ex VAT | 95,00 |
|-------------------|-------|

|  |      |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

|                                       |      |
|---------------------------------------|------|
| Rear window, Scratch(es), E - Replace | 0,00 |
|---------------------------------------|------|



|  |       |
|--|-------|
| Door F L, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Bumper R, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Floor covering F L, Hole, Acceptable                         | 0,00  |
| <i>No pictures to display</i>                                |       |
| Wing R R, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |

