


**AUDI A6: 1GTF483**

Vinnumber:	<b>WAUZZZ4G8EN144329</b>	Versionname:	<b>A6 AVANT Multitr.163PK</b>
First Registrationdate:	<b>23/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>97202</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4527</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/60/16/98 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 2 mm</b>	Fr.R.	<b>Pirelli: 2 mm</b>
	Re.L.	<b>Uniroyal: 2 mm</b>	Re.R.	<b>Uniroyal: 2 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>951,09</b>
Bumper F, Scratch(es), LI - Repair and paint (complete)	<b>254,16</b>



Sill trim R, Scratch(es), It - Spot repair	115,56
--	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

