


**AUDI A5 SPORTBACK: 1KLU773**

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>WAUZZZ8T0FA059095</b> | Versionname: | <b>2.0 TDI 110KW MULTITRONIC</b> |
| First Registrationdate:            | <b>29/05/2015</b>        | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>93358</b>             | Power Kw:    | <b>110</b>                       |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                     |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                   |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3810</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Front parking sensors        |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 | Type of Tow bar              |
| Steering wheel multifunctional | <b>No Tow bar</b>            |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/50/17/94 Y LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 7 mm</b> | Fr.R. | <b>Continental: 7 mm</b> |
|                                  | Re.L. | <b>Michelin: 5 mm</b>    | Re.R. | <b>Michelin: 5 mm</b>    |

**Assistance equipment**

|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 254,16 |
|-------------------|--------|

|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



|                                   |      |
|-----------------------------------|------|
| Wing F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |