



BMW 6 GRAN TURISMO: CF5561			
Vinnumber:	WBAJW61010BM67000	Versionname:	630d (155kW)
First Registrationdate:	16/02/2018	Fiscalpower:	
Expertise Mileage:	30951	Power Kw:	195
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Seats R heated	
GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	245/40/20/99 Y LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: -5 mm

Assistance equipment			
Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2132,43
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 450,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16




Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 348,09





Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00





Protection plate M, Hole, E - Replace

84,00

