



FORD FOCUS CLIPPER: 1PFX251

Vinnumber:	WF06XXGCC6GA05292	Versionname:	1.5 TDCI 77KW S/S ECON 88G BUSINESS ED
First Registrationdate:	27/06/2016	Fiscalpower:	
Expertise Mileage:	120160	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	1406
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------





Total cost ex VAT 121,72

Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Remove lettering	0,00
<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	32,40
	
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Cleaning	25,00
	
Rear window, Scratch(es), E - Replace	0,00
	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Burned, Smart repair	64,32
	
Rocker panel inner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	