



OPEL INSIGNIA SPORTS TOURER: 1TQH090

Vinnumber:	W0VZT8EF6J1080092	Versionname:	1.6 CDTI ecoTEC D 100kW Innovation S/S
First Registrationdate:	11/01/2018	Fiscalpower:	
Expertise Mileage:	64951	Power Kw:	100
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2703
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/94 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1121,91
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80




Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

0,00





Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display