



BMW 4 GRAN COUPE: 1LSF267

Vinnumber:	WBA4E91070G288884	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	20/11/2015	Fiscalpower:	
Expertise Mileage:	139111	Power Kw:	120
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3510
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Total cost ex VAT			506,80
Bonnet, Chemical polution, 67 - Polish			0,00



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tyre repair kit, Missing, E - Replace	252,64
---------------------------------------	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display