



| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| BMW 3: 1JGP501 | | | |
| Vinnumber: | WBA3K11020F835751 | Versionname: | 3 TOURING 318d 136PK |
| First Registrationdate: | 12/12/2014 | Fiscalpower: | |
| Expertise Mileage: | 99142 | Power Kw: | 100 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2505 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Options | | | |
| Radio CD | | Sun Roof electric | |
| GPS storage | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|---------------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | NOT OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| Degree of wear | | | | |
| | 205/60/16/92 W LightMetal | | | |
| Summer tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Goodyear: 3 mm | Re.R. | Goodyear: 3 mm |

| | | | |
|---|------------|------------|----------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1289,40 |
| Bumper grille F L, Missing, E - Replace | | | 0,00 |



Bumper grille F R, Broken, E - Replace

0,00



Bumper grille F L, Broken, E - Replace

0,00



Front end, Dent(s) and scratch(es), Le - Replace and paint

358,40



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Engine protective plate, Broken, E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Broken, Le - Replace and paint

735,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Boot carpet, Stain, Cleaning

25,00



Front end, Dent(s), Le - Replace and paint

171,00

