



## CITROEN C3: RU6372

Vinnumber:	<b>VF7SCBHW6GW579257</b>	Versionname:	<b>1.6 BLUEHDI 75 MAN BUSINESS</b>
First Registrationdate:	<b>10/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>126493</b>	Power Kw:	<b>55</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>NOT OK</b>	Parking lot	<b>1423</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Kleber: 5 mm</b>	Re.R.	<b>Kleber: 5 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>884,44</b>
Door R L, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Roof, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Dent(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing R R, Dent(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wheel cover F L, Scratch(es), E - Replace			<b>24,00</b>



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover R R, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Broken, E - Replace 150,00



Interior, Dirty, Cleaning 40,00



Floor covering F L, Tear, E - Replace 240,00



Maintenance, Maintenance, Execute 0,00



Rearview mirror housing R, Scratch(es), Paint 75,00



Rearview mirror housing L, Scratch(es), Paint 75,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Wheel cover F R, Scratch(es), E - Replace

24,00

