



## CITROEN C4 Picasso: 1HBR422

Vinnumber:	<b>VF73A9HP8EJ669704</b>	Versionname:	<b>GR.C4 PICASSO Business GPS ETG 92PK Aut.</b>
First Registrationdate:	<b>12/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>188165</b>	Power Kw:	<b>68</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3206</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Emergency spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	1082,96
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display


Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wing R L, Dent(s), PDR - Paintless dent repair 82,80



Wing R R, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Bonnet, Chemical pollution, 67 - Polish

0,00

No pictures to display

Floor covering F L, Hole, Smart repair

64,32



Door R R, Bad repair, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display