


FORD TRANSIT: 1GQ188

Vinnumber:	WFOZXXTTGZEY60716	Versionname:	
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	205043	Power Kw:	74
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3431
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Central consol F	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/15/102 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1763,49
Rocker panel inner F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate lock, Broken, E - Replace	350,00



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56



Wing F R, Deformed / Strained, LI - Repair and paint (complete)

165,13



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Sidewall RL (LCV), Dent(s), It - Spot repair

115,56



Model badge R, Strained , E - Replace

40,00



Brand badge, Broken, E - Replace

40,00



Seat cover R, Hole, Smart repair

64,32



Rocker panel inner F L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Sill outer R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

395,40



Bodywork, Not original part, Acceptable

0,00



Instrument panel covers, Hole, Acceptable

0,00

No pictures to display