



BMW 5 BERLINE: 1KLX331

Vinnumber:	WBA5E51080G102394	Versionname:	2.0 520D (120KW)
First Registrationdate:	29/05/2015	Fiscalpower:	
Expertise Mileage:	195634	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	LCV
Maintenance:	SERVICE -4000KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L. Bridgestone: 7 mm	Fr.R. Bridgestone: 7 mm	
	Re.L. Bridgestone: 7 mm	Re.R. Bridgestone: 7 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1410,73
-------------------	----------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Floor covering F L, Burned, Smart repair 64,32



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Reflector, Broken, E - Replace 30,45



Bumper R, Crack, Le - Replace and paint 766,80



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), I - Repair 100,00



Alloy rim R R, Scratch(es), I - Repair 100,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16

