



LAND ROVER RANGE ROVER EVOQUE: 1LUR802

Vinnumber:	SALVA2DN7GH102291	Versionname:	2.0 TD4 110KW SE DYNAMIC 4WD
First Registrationdate:	9/12/2015	Fiscalpower:	
Expertise Mileage:	100728	Power Kw:	110
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2829
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/107 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	2932,57
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02



Roof, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R 3P, Scratch(es), It - Spot repair 115,56



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Bumper moulding F M, Scratch(es), Smart repair 110,64



Wing F L, Scratch(es), It - Spot repair 115,56



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16





Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Bumper cover R M, Scratch(es), Smart repair

110,64



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display