



VOLKSWAGEN TOURAN: SF8428

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber: | WVGZZZ1TZFW086548 | Versionname: | 1.6 CR TDI TRENDLINE BLUEMOTION TECH |
| First Registrationdate: | 1/06/2015 | Fiscalpower: | |
| Expertise Mileage: | 160919 | Power Kw: | 77 |
| Bodytype: | MPV | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1526 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|-------------------------|------------------------------|-----------------|-------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 H Steel | | | |
| Summer tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 231,12 |
| Wheel cover F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper F, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wheel cover R R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) | | | 115,56 |



| | |
|---|--------|
| Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) | 115,56 |
|---|--------|



| | |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Door F L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display