



OPEL Movano 3500 MWB Med.High Roof: FA5006

Vinnumber:	WOLMRA4RCFB072518	Versionname:	MOVANO 3500 B/F2C L2H2(E5)110PK
First Registrationdate:	23/01/2015	Fiscalpower:	
Expertise Mileage:	151892	Power Kw:	81
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV23
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/55/16/110 R Steel				
Summer tyres:	Fr.L.	Continental: 1 mm	Fr.R.	Continental: 1 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	954,93
Trunk door R R, Dent(s), PDR - Paintless dent repair	82,80



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper grille, Deformed / Strained, Acceptable

0,00

No pictures to display

Wing R R, Bad repair, Acceptable

0,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

313,56



Door F R, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Missing, E - Replace

22,50



Roof, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Missing, E - Replace

22,50



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13

