


PEUGEOT 308 SW: 1PDT377

Vinnumber:	VF3LCBHXHGS142648	Versionname:	1.6 BLUEHDI 85KW S/S 88G ALLURE
First Registrationdate:	26/05/2016	Fiscalpower:	
Expertise Mileage:	200967	Power Kw:	85
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

	Compressor	Yes
Total cost ex VAT		63,00
Bodywork, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Tear, E - Replace		0,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00

