



VOLKSWAGEN Polo: 1DWY133

Vinnnumber:	WVWZZZ6RZDY037507	Versionname:	POLO Comfortline DPF 75PK
First Registrationdate:	21/09/2012	Fiscalpower:	
Expertise Mileage:	144094	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4804
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			711,58
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)			176,14



Roof, Hail damage, PDR - Hail

0,00



Wheel cover F R, Scratch(es), E - Replace

24,00



Luggage space cover, Missing, E - Replace

192,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Hail damage, PDR - Hail

0,00



