



**PEUGEOT 5008: 1GRY573**

|                                    |                          |              |                          |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber:                         | <b>VF30A9HD8E5074535</b> | Versionname: | <b>5008 Active 115PK</b> |
| First Registrationdate:            | <b>11/04/2014</b>        | Fiscalpower: |                          |
| Expertise Mileage:                 | <b>114627</b>            | Power Kw:    | <b>84</b>                |
| Bodytype:                          |                          | Body color:  | <b>Beige</b>             |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4104</b>              |
| Number of doors:                   | <b>5</b>                 |              |                          |
| Number of seats:                   | <b>5</b>                 |              |                          |
| Number head rests:                 | <b>5</b>                 |              |                          |
| Rims summer:                       | <b>Aluminium</b>         |              |                          |
| Category:                          | <b>Passenger Car</b>     |              |                          |
| Oil level:                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                          |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Panoramic roof        |                   |
| Windows electric F             |                              | Luggage cover         |                   |
| Windows electric R             |                              | Front parking sensors |                   |
| Cruise Control                 |                              | Rear parking sensors  |                   |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                             |       |                       |       |                       |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| <b>215/55/16/93 H Steel</b> |       |                       |       |                       |
| Summer tyres:               | Fr.L. | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                             | Re.L. | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|   |               |
|---|---------------|
| <b>Total cost ex VAT</b>                    | <b>158,00</b> |
| <b>Windscreen, Scratch(es), E - Replace</b> | <b>0,00</b>   |



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display