


VOLKSWAGEN Golf Sportsvan: 1HVZ980

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | WVWZZZAUZFW547009 | Versionname: | GOLF SPORTSVAN Trendline 90PK |
| First Registrationdate: | 17/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 57394 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Beige |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2431 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Sun Roof electric | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | No Tow bar |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |
| Adaptive cruise control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 H Steel | | | |
| Summer tyres: | Fr.L. | Michelin: 2 mm | Fr.R. | Michelin: 2 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|--|------------|------|---------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 315,80 |
| Protection plate M, Deformed / Strained, E - Replace | | | 74,00 |



Wheel cover R R, Scratch(es), E - Replace

30,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display