


**BMW 3 BERLINE: 1KEN184**

|                                   |                          |              |                                 |
|-----------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                        | <b>WBA3D11070F330623</b> | Versionname: | <b>2.0 318D (100KW) BERLINE</b> |
| First Registrationdate:           | <b>15/04/2015</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                | <b>154935</b>            | Power Kw:    | <b>100</b>                      |
| Bodytype:                         |                          | Body color   | <b>Brown</b>                    |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                  |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                       |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3624</b>                     |
| Number of doors                   | <b>4</b>                 |              |                                 |
| Number of seats                   | <b>5</b>                 |              |                                 |
| Number head rests                 | <b>5</b>                 |              |                                 |
| Rims summer                       | <b>Aluminium</b>         |              |                                 |
| Category                          | <b>Passenger Car</b>     |              |                                 |
| Oil level                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                 |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional | Type of Tow bar                  |
| Radio multimedia               | <b>Tow bar fixed</b>             |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres: | 225/60/16/98 V LightMetal |                   |       |                   |
|               | Fr.L.                     | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
|               | Re.L.                     | Bridgestone: 4 mm | Re.R. | Bridgestone: 4 mm |

**Assistance equipment**

|                                               |          |  |               |
|-----------------------------------------------|----------|--|---------------|
| Number of charging cables (normal)            | <b>0</b> |  |               |
| Number of charging cables (rapid charge)      | <b>0</b> |  |               |
| <b>Total cost ex VAT</b>                      |          |  | <b>220,18</b> |
| <b>Door R R, Scratch(es), Acceptable</b>      |          |  | <b>0,00</b>   |
| <i>No pictures to display</i>                 |          |  |               |
| <b>Bumper R, Scratch(es), Acceptable</b>      |          |  | <b>0,00</b>   |
| <i>No pictures to display</i>                 |          |  |               |
| <b>Alloy rim F R, Scratch(es), Acceptable</b> |          |  | <b>0,00</b>   |
| <i>No pictures to display</i>                 |          |  |               |
| <b>Alloy rim R R, Scratch(es), Acceptable</b> |          |  | <b>0,00</b>   |

|                                        |      |
|----------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |
|---------------------------------------------------------------------|--------|

