



RENAULT CLIO: 1KNF498				
Vinnumber:	VF15RJL0H52519220	Versionname:	1.5 ENERGY DCI 90E EXPRESSION	
First Registrationdate:	2/06/2015	Fiscalpower:		
Expertise Mileage:	72556	Power Kw:	66	
Bodytype:	Hatchback	Body color	Silver	
Gearbox:	MAN 5 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	2822	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
GPS storage	HD	Luggage cover		
GPS storage		Rear parking sensors		
Windows electric F		Type of Tow bar	No Tow bar	
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	185/55/15/92 V Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			1075,38	
Wheel cover R R, Scratch(es), E - Replace			24,00	



Wheel cover F L, Scratch(es), E - Replace

24,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

24,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable


0,00

No pictures to display

Rear spoiler, Chemical pollution, LI - Repair and paint (complete)


115,56





Roof, Chemical polution, LI - Repair and paint (complete)

385,20




Wing R R, Scratch(es), LI - Repair and paint (complete)

246,56



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,06



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Broken, E - Replace

24,00



