


MERCEDES B: 1KSU864

Vinnumber:	WDD2462121J345244	Versionname:	1.5 B 180 CDI
First Registrationdate:	25/06/2015	Fiscalpower:	
Expertise Mileage:	64457	Power Kw:	80
Bodytype:	MPV	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3829
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1760,46
Compressor, Missing, E - Replace	0,00



Wheel cover F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover R R, Scratch(es), E - Replace	30,00



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Tyre repair kit, Missing, E - Replace	210,53



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

Door L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00
	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Wing R R, Dent(s), PDR - Paintless dent repair	63,00
	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wheel cover R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display