



RENAULT CLIO: 1KNF149

Vinnumber:	VF15RJL0H53062263	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	67062	Power Kw:	66
Bodytype:	Hatchback	Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3527
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	402,08
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper cover R M, Scratch(es), Smart repair	110,64



Wheel cover F R, Scratch(es), E - Replace

24,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Door F R, Bad repair, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Protection plate M, Deformed / Strained, E - Replace	74,00



Wheel cover R L, Scratch(es), Acceptable	0,00
No pictures to display	