


VOLVO V60: 1HNV669

Vinnumber:	YV1FW8481F1225433	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	76504	Power Kw:	84
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2310
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar removable
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			967,34
Grill frame, Broken, E - Replace			266,74



Luggage space cover, Incomplete, E - Replace	0,00
--	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tyre R R, Flat, E - Replace	132,00
-----------------------------	--------



Door frame R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover R L, Stain, Cleaning	25,00
---------------------------------	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Boot carpet, Stain, Cleaning	25,00
------------------------------	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door F L, Scratch(es), Acceptable		0,00
No pictures to display		
Door frame F R, Dent(s), Acceptable		0,00
No pictures to display		