



VOLKSWAGEN PASSAT VARIANT: 1LBD580

Vinnumber:	WVWZZZ3CZGE044508	Versionname:	2.0 TDI VARIANT COMFORTLINE
First Registrationdate:	7/08/2015	Fiscalpower:	
Expertise Mileage:	178909	Power Kw:	110
Bodytype:	Break	Body color	Light Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1104
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar fixed
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/94 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Bridgestone: 5 mm	Re.R.

Assistance equipment

Spare wheel	Yes	Compressor	Yes
Repair kit	Yes		
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2273,38
-------------------	---------

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

