



RENAULT CLIO: 1KNF125

Vinnumber:	VF15RJOH53062235	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	79247	Power Kw:	66
Bodytype:	Hatchback	Body color	Red
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3704
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.
	Re.L.	Michelin: 4 mm	Re.R.

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	902,74
-------------------	--------

Wing R R, Dent(s), LI - Repair and paint (complete)	246,56
---	--------



Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	169,44
---	--------

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)		0,00
    		
Wheel cover F L, Scratch(es), Acceptable		0,00
No pictures to display		
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)		232,06
  		
Door R R, Scratch(es), LI - Repair and paint (complete)		254,68
   		
Seat cover F L, Worn, Acceptable		0,00
  		
Wing R L, Scratch(es), 67 - Polish		0,00
No pictures to display		
Roof, Dent(s), Acceptable		0,00
No pictures to display		
Wheel cover F R, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Door R L, Scratch(es), Acceptable		0,00
No pictures to display		