



RENAULT Megane: 1HHY829

Vinnumber:	VF1KZ0R0251353035	Versionname:	MEGANE GT TomTom Edition 95PK
First Registrationdate:	29/07/2014	Fiscalpower:	
Expertise Mileage:	133346	Power Kw:	70
Bodytype:	Break	Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1725
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1060,50
-------------------	---------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Window F R door, Scratch(es), E - Replace

119,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace

30,00



Bonnet, Chemical polution, Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35





Bumper cover R M, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display