


VOLKSWAGEN Golf: 1GIL169

Vinnumber:	WVWZZZAUZEW278402	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	17/02/2014	Fiscalpower:	
Expertise Mileage:	174227	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3509
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1013,28
Bumper R, Crack, Le - Replace and paint	0,00



Bumper F, Crack, Le - Replace and paint

0,00




Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Roof, Dent(s), LI - Repair and paint (complete)

481,50



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Boot carpet, Dirty, Cleaning

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable



0,00


No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display





Seat cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	