



VOLKSWAGEN POLO: 1JUA865

Vinnnumber:	WVWZZZ6RZFY251168	Versionname:	1.4 TDI 66KW COMFORTLINE BMT
First Registrationdate:	25/02/2015	Fiscalpower:	
Expertise Mileage:	62908	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1105
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining fabrics
	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	535,58
-------------------	---------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

176,14

