



|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| <b>CITROEN C3: RU6371</b>          |                          |              |                                    |
| Vinnumber:                         | <b>VF7SCBHW6GW579258</b> | Versionname: | <b>1.6 BLUEHDI 75 MAN BUSINESS</b> |
| First Registrationdate:            | <b>10/06/2016</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>134706</b>            | Power Kw:    | <b>55</b>                          |
| Bodytype:                          |                          | Body color:  | <b>White</b>                       |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Opaque</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                       |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4630</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Steel</b>             |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

|                         |                              |                      |                   |
|-------------------------|------------------------------|----------------------|-------------------|
| <b>Options</b>          |                              |                      |                   |
| Radio CD                |                              | Luggage cover        |                   |
| Windows electric F      |                              | Rear parking sensors |                   |
| Cruise Control          |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Type of headlighting    | <b>Headlighting Halogen</b>  |                      |                   |
| Type of Lining          | <b>Lining fabrics</b>        |                      |                   |
| Type of climate control | <b>Autom climate control</b> |                      |                   |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                             |                       |       |                       |
|-----------------------|-----------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                             |                       |       |                       |
|                       | <b>185/65/15/88 T Steel</b> |                       |       |                       |
| Summer tyres:         | Fr.L.                       | <b>Kleber: 3 mm</b>   | Fr.R. | <b>Kleber: 3 mm</b>   |
|                       | Re.L.                       | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

|  |            |      |                |
|--|------------|------|----------------|
| <b>Assistance equipment</b>              |            |      |                |
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b>     |
| Total cost ex VAT                        |            |      | <b>1385,54</b> |
| Floor covering F L, Damaged, E - Replace |            |      | <b>240,00</b>  |



|  |  |             |
|--|--|-------------|
| Door F L, Dent(s), Acceptable          |  | <b>0,00</b> |
| <i>No pictures to display</i>          |  |             |
| Maintenance book, Missing, E - Replace |  | <b>0,00</b> |
| <i>No pictures to display</i>          |  |             |

no pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Broken, Le - Replace and paint 535,20



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 24,00



Fire extinguisher, Missing, E - Replace 12,00



Bodywork, Chemical polution, Cleaning 100,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Spoiler R, Damaged, E - Replace 35,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Ignition key, Broken, E - Replace 150,00



Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 265,34



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*