



AUDI Q5: DR1010

Vinnumber:	WAUZZFY7J2069544	Versionname:	2.0 TFSi S tronic quattro Sport
First Registrationdate:	1/12/2017	Fiscalpower:	
Expertise Mileage:	34910	Power Kw:	185
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/18/107 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3020,01
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Outer backrest protection L, Tear, Smart repair

110,64



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)

348,09



Rearview mirror basis L, Scratch(es), Smart repair

110,64



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Roof, Scratch(es), LI - Repair and paint (complete) 577,80



Wing moulding F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing trim R R, Scratch(es), Le - Replace and paint 120,00



Door panel F L, Tear, Smart repair 110,64



