



AUDI A4: 1FLQ769			
Vinnumber:	WAUZZZ8K8EN010077	Versionname:	A4 BER TDie 136PK
First Registrationdate:	8/08/2013	Fiscalpower:	
Expertise Mileage:	159127	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4602
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	CD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2013,07
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Rearview mirror R complete, Missing, Le - Replace and paint 283,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display


Door R R, Dent(s) and scratch(es), Le - Replace and paint 946,92



Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



