



AUDI A3 SPORTBACK: 1LAE879

Vinnumber:	WAUZZZ8V9FA186591	Versionname:	2.0 TDI 110KW AMBITION
First Registrationdate:	31/07/2015	Fiscalpower:	
Expertise Mileage:	54782	Power Kw:	110
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3124
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/40/18/92 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	385,08
-------------------	---------------

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	-------------

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Bumper R, Bad repair, Acceptable

0,00

