



AUDI A3: 1HER905

Vinnumber:	WAUZZZ8V5EA175683	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	2/07/2014	Fiscalpower:	
Expertise Mileage:	141300	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	DANS 7600 KMS OU 89 JOURS	Parking lot:	4208
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	559,60
-------------------	---------------

Roof, Chemical polution, 67 - Polish	0,00
--------------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Floor covering F R, Dirty, Cleaning

25,00



Roof, Hail damage, PDR - Hail

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair

63,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display