



**AUDI A4: 1HBV883**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WAUZZZ8K9EA153627</b> | Versionname: | <b>A4 AVANT TDie 136PK</b> |
| First Registrationdate:            | <b>13/06/2014</b>        | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>120447</b>            | Power Kw:    | <b>100</b>                 |
| Bodytype:                          |                          | Body color:  | <b>Brown</b>               |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3512</b>                |
| Battery functioning:               | <b>Yes</b>               |              |                            |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| GPS storage                    | Luggage cover                |
| GPS storage                    | CD                           |
| Windows electric F             | Rear parking sensors         |
| Windows electric R             |                              |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                     |       |                     |
|----------------------------------|-------|---------------------|-------|---------------------|
| <b>205/60/16/92 H LightMetal</b> |       |                     |       |                     |
| Summer tyres:                    | Fr.L. | <b>Dunlop: 4 mm</b> | Fr.R. | <b>Dunlop: 4 mm</b> |
|                                  | Re.L. | <b>Dunlop: 5 mm</b> | Re.R. | <b>Dunlop: 5 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                                      |               |
|--------------------------------------|---------------|
| Total cost ex VAT                    | <b>211,80</b> |
| Rear window, Scratch(es), Acceptable | <b>0,00</b>   |



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80

