



CITROEN C4 Picasso: 1HFB579

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | VF73A9HC8DJ866991 | Versionname: | GR.C4 PICASSO Intensive ETG 115PK Aut. |
| First Registrationdate: | 4/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 84329 | Power Kw: | 85 |
| Bodytype: | MPV | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2401 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| | Tow bar removable |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/17/95 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | |
|---|--------|
| Total cost ex VAT | 866,58 |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |





Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), 67 - Polish 0,00

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wing F R, Chemical polution, 67 - Polish 0,00

No pictures to display