



HYUNDAI GRAND SANTA FE: VJ8680

Vinnumber:	KMHSR81XDFU125302	Versionname:	2.2 CRDI 4WD AUTO EXECUTIVE
First Registrationdate:	10/08/2015	Fiscalpower:	
Expertise Mileage:	110453	Power Kw:	145
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1506
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/19/101 H LightMetal				
Summer tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	941,64
-------------------	---------------

Central pillar L, Scratch(es), It - Spot repair	115,56
---	---------------



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Registration Document, Damaged, E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Interior, Dirty, Cleaning 50,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair 110,64



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper moulding R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display