


FORD FIESTA: 1KDV795

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | WF0DXXGAKDFE05101 | Versionname: | 1.6 TDCI S/S TREND ECONETIC |
| First Registrationdate: | 10/04/2015 | Fiscalpower: | |
| Expertise Mileage: | 141983 | Power Kw: | 70 |
| Bodytype: | Hatchback | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1225 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|-------------------|
| Radio CD | Luggage cover | |
| Windows electric F | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|------------------------|-------|------------------------|
| | 175/65/14/82 H Steel | | | |
| Summer tyres: | Fr.L. | Firestone: 6 mm | Fr.R. | Firestone: 6 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | |
|-------------|------------|
| Spare wheel | Yes |
|-------------|------------|

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|---|------|
| Bodywork, Not original part, Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|--|------|
| Wheel cover R L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---------------------------|------|
| Roof, Dent(s), Acceptable | 0,00 |
|---------------------------|------|

No pictures to display

| | |
|--|------|
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display