



**MERCEDES CLA: 1WMF620**

Vinnumber:	<b>WDD1173031N342593</b>	Versionname:	<b>2.1 CLA 220 D 120KW AMG LINE</b>
First Registrationdate:	<b>15/02/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>140967</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2330</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/40/18/92 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Fulda: 5 mm</b>	Re.R.	<b>Fulda: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>603,35</b>
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Alloy rim F R polished, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

