



MERCEDES CLA SHOOTING BRAKE: 1KLX303

Vinnnummer:	WDD1179081N229898	Versionname:	2.1 CLA 200 CDI SHOOTING BRAKE
First Registrationdate:	29/05/2015	Fiscalpower:	
Expertise Mileage:	100794	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1328
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	259,80
-------------------	--------

Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

No pictures to display

Wing R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display