



**OPEL COMBO: 1PFL533**

Vinnumber:	<b>W0L6ZYC1AH9596153</b>	Versionname:	<b>1.3 CDTI 66KW 2.0T SWB</b>
First Registrationdate:	<b>23/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>56202</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV06</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>185/65/15/92 T LightMetal</b>			
Summer tyres:	Fr.L. <b>Pirelli: 4 mm</b>	Fr.R. <b>Pirelli: 4 mm</b>	
	Re.L. <b>Pirelli: 7 mm</b>	Re.R. <b>Pirelli: 7 mm</b>	

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	610,93
-------------------	--------

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Seat cover F L, Hole, E - Replace	300,00
-----------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

no pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display


Wing R R, Dent(s), PDR - Paintless dent repair 82,80



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Wing R L, Dent(s), PDR - Paintless dent repair 63,00

