



OPEL COMBO: 1PFL534

Vinnumber:	WOL6ZYC1AH9596145	Versionname:	1.3 CDTI 66KW 2.0T SWB
First Registrationdate:	23/06/2016	Fiscalpower:	
Expertise Mileage:	83575	Power Kw:	66
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU20
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	947,30
-------------------	---------------

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	---------------





Trunk door R L, Dent(s), PDR - Paintless dent repair

63,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76




Steel rim F R, Deformed / Strained, E - Replace

72,60



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15

