



MERCEDES CLA: 1KGK426

| | | | |
|-----------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WDD1173121N204630 | Versionname: | 1.5 CLA 180 CDI URBAN |
| First Registrationdate: | 28/04/2015 | Fiscalpower: | |
| Expertise Mileage: | 32970 | Power Kw: | 80 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance | ASS A3 PLUS 300 D | Parking lot: | LCV |
| Maintenance | OK | | |
| Battery functioning | Yes | | |
| Number of doors | 4 | | |
| Number of seats | 5 | | |
| Number head rests | 1 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Front parking sensors |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-leather | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 225/45/17/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Yokohama: 3 mm | Fr.R. | Yokohama: 3 mm |
| | Re.L. | Yokohama: 6 mm | Re.R. | Yokohama: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1074,00 |
|-------------------|----------------|

| | |
|-----------------------------|---------------|
| Tyre F R, Worn, E - Replace | 132,00 |
|-----------------------------|---------------|



Bumper F, Bad repair, LI - Repair and paint (complete)

211,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Alloy rim F R polished, Scratch(es), E - Replace

235,20



Door R L, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim R R polished, Scratch(es), E - Replace

235,20



Door F L, Dent(s), Acceptable

0,00

