



SEAT Alhambra: 1GWW665

Vinnumber:	VSSZZZ7NZEV519300	Versionname:	ALHAMBRA Ecom.Style DPF 136PK
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	167431	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4115
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1484,59
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Internal Boot Lining R, Broken, Smart repair			110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Internal Boot Lining R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Damaged, Smart repair 64,32



Boot carpet, Dirty, Cleaning 25,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Tyre repair kit, Missing, E - Replace 210,53

No pictures to display