



RENAULT CLIO: 1KNF591

Vinnumber:	VF15RJL0H52519267	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	80332	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2827
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2069,02
-------------------	---------

Wheel cover R L, Broken, E - Replace	24,00
--------------------------------------	-------



Wheel cover F R, Broken, E - Replace	24,00
--------------------------------------	-------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00



Wheel cover R R, Scratch(es), E - Replace 24,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Rear window, Scratch(es), E - Replace 320,00



Bonnet, Dent(s), LI - Repair and paint (complete) 232,06



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wheel cover F L, Broken, E - Replace 24,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Interior, Dirty, Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Smart repair 110,64



Seat cover R, Burned, Smart repair 64,32



Radio, Crack, E - Replace 210,00



Door F R, Dent(s), LI - Repair and paint (complete) 254,68

